





33-11-001 , De-icing , Heated rear window


- ◆ → 95
- ◆◆ 95 → 95 1/2
- ◆◆◆ 95 1/2 →







33-11-002, De-icing

- ◆ → 95
- ◆◆ 95 → 95 1/2
- ◆◆◆ 95 1/2 →







33-11-003 , De-icing , before 95, RS Cosworth Heated windscreen



01 100 178 811



33-11-004 , De-icing , As of 95 without RS Cosworth Heated windscreen





G1002



G1002

33-11-005 , De-icing , Heated mirrors

- ◆ → 95
- ◆◆ 95 → 95 ½
- ◆◆◆ 95 ½ →

* except RS Cosworth

